













<p><b>M10</b> (4.5X40X115-φ13) S=75 枠空き:70</p> 	<p><b>M12</b> (6X52X155-φ17) S=100 枠空き:100</p> 	<p><b>M14</b> (6X52X155-φ17) S=115 枠空き:115:</p> 																																																	
<p><b>M16</b> (6X52X170-φ17) S=125 枠空き:120</p> 	<p><b>M18</b> (9X67X190-φ21.5) S=140 枠空き:140</p> 	<p><b>M20</b> (9X67X205-φ21.5) S=150 枠空き:150</p> 																																																	
<p><b>M22</b> (9X77X230-φ23.5) S=165 枠空き:165</p> 	<p><b>M24</b> (9X77X280-φ21.5) S=175 枠空き:170</p> 	<p><b>M27</b> (9X92X285-φ21.5) S=200 枠空き:200</p> 																																																	
<p><b>M30</b> (12X92X310-φ23.5) S=200 枠空き:200</p> 	<table border="1"> <thead> <tr> <th>サイズ</th> <th>割枠(kg)</th> <th>板(kg)</th> <th>サイズ</th> <th>割枠(kg)</th> <th>板(kg)</th> </tr> </thead> <tbody> <tr> <td>M10</td> <td>0.17</td> <td>0.07</td> <td>M24</td> <td>2.12</td> <td>1.26</td> </tr> <tr> <td>M12</td> <td>0.33</td> <td>0.34</td> <td>M27</td> <td>3.09</td> <td>1.55</td> </tr> <tr> <td>M14</td> <td>0.54</td> <td>0.34</td> <td>M30</td> <td>3.94</td> <td>2.25</td> </tr> <tr> <td>M16</td> <td>0.72</td> <td>0.37</td> <td colspan="3">JIS 外</td> </tr> <tr> <td>M18</td> <td>1.01</td> <td>0.8</td> <td>W3/8</td> <td>0.02</td> <td>0.07</td> </tr> <tr> <td>M20</td> <td>1.3</td> <td>0.87</td> <td>W1/2</td> <td>0.3</td> <td>0.17</td> </tr> <tr> <td>M22</td> <td>1.64</td> <td>1.11</td> <td>W5/8</td> <td>0.5</td> <td>0.3</td> </tr> </tbody> </table>			サイズ	割枠(kg)	板(kg)	サイズ	割枠(kg)	板(kg)	M10	0.17	0.07	M24	2.12	1.26	M12	0.33	0.34	M27	3.09	1.55	M14	0.54	0.34	M30	3.94	2.25	M16	0.72	0.37	JIS 外			M18	1.01	0.8	W3/8	0.02	0.07	M20	1.3	0.87	W1/2	0.3	0.17	M22	1.64	1.11	W5/8	0.5	0.3
サイズ	割枠(kg)	板(kg)	サイズ	割枠(kg)	板(kg)																																														
M10	0.17	0.07	M24	2.12	1.26																																														
M12	0.33	0.34	M27	3.09	1.55																																														
M14	0.54	0.34	M30	3.94	2.25																																														
M16	0.72	0.37	JIS 外																																																
M18	1.01	0.8	W3/8	0.02	0.07																																														
M20	1.3	0.87	W1/2	0.3	0.17																																														
M22	1.64	1.11	W5/8	0.5	0.3																																														
<p><b>W3/8</b> (3X38X90-φ11) S=75 枠空き:75</p> 	<p><b>W1/2</b> (4.5X46X122-φ14) S=100 枠空き:120</p> 	<p><b>W5/8</b> (6X50X150-φ18) S=120 枠空き:140</p> 